

Installation: CF30 controller software

System requirements:

Win2000, Windows XP, Windows Vista

1) Connect the USB-Piezo-Controller to the computer.

The computer recognizes the new USB-Hardware.

2) The computer automatically ask for the path of the driver.

The driver software is on the CD in the following directory:

\CDM 2.04.06 WHQL Certified\

The two relevant files are:

FTDIBUS.inf

FTDIPORT.inf

(restart the computer)

3) Start "CF30Setup.msi"